Oil Field Environmental Incident Summary

Incident: 20140517142713 Date/Time of Notice: 05/17/2014 14:27

Responsible Party: BURLINGTON RESOURCES OIL & GAS COMPANY LP

Well Operator: BURLINGTON RESOURCES OIL & GAS COMPANY LP

Well Name: ARCHER 44-25TFH

Field Name: CHARLSON Well File #: 25960

Date Incident: 5/17/2014 Time Incident: 05:00 Facility ID Number:

County: MCKENZIE Twp: 153 Rng: 95 Sec: 25 Qtr: SE SE

Location Description: Oil was discharged to the flare. As a result, the flare was extinguished and a

light mist of oil drifted off of the North East side of the well pad.

Submitted By: Lewis Schoenberger Received By:

Contact Person: Lewis Schoenberger

PO BOX 51810

MIDLAND, TX 79710-1810

General Land Use: Pasture Affected Medium: Topsoil

Distance Nearest Occupied Building: 1 Mile
Distance Nearest Water Well: 1 Mile

Type of Incident: Other

Release Contained in Dike: No Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil 6 Gallons

Brine Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 8/3/2016 Clean Up Concluded: 5/27/2014

Risk Evaluation:

None

Areal Extent:

approximately 110 feet by 100 feet off of the Northeast side of the well pad.

Potential Environmental Impacts:

None

Action Taken or Planned:

We will work with property owner to collect oil impacted material for appropriate disposal.

Wastes Disposal Location: Yet to be determined.

Agencies Involved:

Updates

Date: 5/19/2014 Status: Inspection Author: Washek, Sandi

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

5-19-2014 5:19 p.m. on location. Called company rep to discuss cleanup of vegetation that was impacted by treater upset through the flare. Material was observed along the flare and over the fence line into pasture land about 50 x50 feet. Company working with landowner on cleanup plan to cut and remove impacted vegatation. Company rep will contact NDDoH when completed.

Date: 5/19/2014 Status: Reviewed - Follow-up Required Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Treater upset extinguished flare and sprayed off location. Followup is necessary.